Scope of	Work for Property Loc	ated at:		1919 West Gale	ena Street	
	Property is: Single Fan	nily 🗹	Duplex	□ Other □		
Date:						
take no respo		after the ins	ection date	e, or for omissions throu	s, the Redevelopment Authority, and their rugh error or oversight. The list does not ne IE programs.	
Exterior (	Condition Report					
Location Site	Required Work Landscaping	n/a 🔽	Yes 🗌	Note/Comments Self Help	\$	Cost
	Steps/Handrails	n/a 🔽	Yes 🗌		\$	
	Service walks	n/a 🗸	Yes 🗌		\$	
	Fencing	n/a 🗸	Yes 🗌		\$	
	Parking	n/a 🔽	Yes 🗌		\$	
	Retaining walls	n/a 🔽	Yes 🗌		\$	
	Other	n/a 🗌	Yes 🗌			
_	Other	n/a 🔲	Yes 🗌		\$	
Garage	Singles: repair	n/a 🔲	Yes 🗌		\$	
	Shingles: Roof over existing	n/a 🗌	Yes 🗌			
	Shingles:Tear off & re-roof	n/a 🗌	Yes 🗌		\$	
	Gutters/downspouts	n/a 🗌	Yes 🗌		\$	
	Flashing	n/a 🗌	Yes 🗌		\$	
	Eaves	n/a 🗌	Yes 🗌		\$	
	Siding	n/a 🔲	Yes 🗌		\$	
	Doors	n/a 🔲	Yes 🗌		\$	
	Windows	n/a 🗌	Yes 🗌		\$	
	Slab	n/a 🗌	Yes 🗌		\$	
	Paint	n/a 🗌	Yes 🗌		\$	
Porches	Electrical	n/a 🗌	Yes 🗌		\$	
	Other	n/a 🗌	Yes 🗌		\$	
	Roof	n/a 🗸	Yes 🗌	_	\$	
	Deck-upper	n/a 🗸	Yes 🗌		\$	
	Decklower	n/a 🗸	Yes 🗌		\$	
	Steps/handrails	n/a	Yes 🗸	Stairs and handrails	s \$	800.00
	Ceiling	n/a 🔽	Yes 🗌	_	\$	
	Guardrails	n/a	Yes 🗸	repairs	\$	200.00
	Structural	n/a 🗸	Yes 🗌		\$	
	Paint	n/a 🗌	Yes 🗸	all	\$	400.00

n/a Yes reapr porch stairs and paint

Other

\$

600.00

## House

Chimney	n/a ☑ Yes 🗌	\$
Shingles: repair	n/a ✓ Yes 🗌	\$
Shingles: Roof over existing	n/a ☑ Yes 🗌	\$
Shingles:Tear off & re-roof	n/a ☐ Yes ☑	\$ 7,000.00
Gutters/downspouts	n/a ☐ Yes ☑	\$ 800.00
Flashing	n/a ☑ Yes 🗌	\$
Eaves	n/a Yes <u>repairs</u>	\$ 500.00
Siding	n/a ☑ Yes □	\$
Storm Doors	n/a ☑ Yes □	\$
Prime ("main") Doors	n/a ☐ Yes ☑	\$ 750.00
Storm Windows	n/a ☑ Yes 🗌	\$
Prime ("main") Windows	n/a ☐ Yes ☑	\$ 2,500.00
Paint	n/a ☐ Yes ☑ <b>all trim</b>	\$ 1,500.00
Foundation	n/a ☑ Yes □	\$
Electrical	n/a ☑ Yes □	\$
Other	n/a Yes	\$
Other	n/a  Yes	\$
Other	n/a  Yes	\$
Other	n/a  Yes	\$

Exterior: Estimated Cost:\* \$

\*average contracted cost. Actual costs may vary. Self help will reduce the amount.

15,050.00

Interior Co	ondition Report						
	<b>Unit:</b> Entire unit (single family) Upper unit of duplex	✓ □				Lower unit of duplex  Other	
Mechanical Heating	Required Work						
	Repair/replace boiler	n/a	<b>V</b>	Yes		-	\$ 
	Repair radiation	n/a	<b>V</b>	Yes			\$ 
	Repair/replace furnace	n/a	<b>V</b>	Yes			\$
	Repair ductwork	n/a	7	Yes			\$
	Replace thermostat	n/a	7	Yes			\$
	Repair/replace grilles	n/a	7	Yes			\$
Electrical	Tune boiler/furn. insp ht exchang	€n/a		Yes	<b>V</b>		\$ 250.00
Liectrical	Repair/replace receptacles	n/a		Yes	<b>V</b>		\$ 100.00
	Repair/replace switches	n/a		Yes	1	-	\$ 100.00
	Repair/replace fixtures	n/a		Yes	1	7	\$ 250.00
	Install outlets and circuits	n/a	<b>V</b>	Yes			\$
	Install outlets and circuits	n/a	<b>V</b>	Yes			\$
	Install outlets and circuits	n/a	<b>V</b>	Yes			\$
	Install outlets and circuits	n/a	<b>y</b>	Yes			\$
	Upgrade service	n/a	<b>V</b>	Yes			\$
	Other	n/a		Yes	1	missing hardwired smoke detectors	\$ 250.00
	Other	n/a		Yes			\$ 
Plumbing	Repair/replace kitchen sink	n/a		Yes			\$
	Repair/replace kitchen sink fauce	e n/a		Yes			\$
	Repair/replace tub	n/a	<b>4</b>	Yes			\$
	Repair/replace tub faucet	n/a	7	Yes			\$
	Repair/replace toilet	n/a		Yes	1		\$ 250.00
	Repair/replace lavatory	n/a		Yes	7		\$ 400.00
	Repair/replace lavatory faucet	n/a	7	Yes			\$
	Repair/replace wash tub	n/a	7	Yes			\$ 
	Repair/replace wash tub faucet	n/a	7	Yes			\$
	Unclog piping:	n/a	7	Yes			\$
	Repair drain/waste/vent piping	n/a	7	Yes			\$
	Repair water piping	n/a	<b>V</b>	Yes			\$ 
	Repair/replace water heater	n/a	7	Yes			\$ 
	Other	n/a		Yes	<b>J</b>	complete kitchen	\$ 1,500.00
	Other	n/a		Yes			\$ 

Windows								
	Replace broken glass	n/a [	<b>J</b>	Yes		=	\$	
	Repair or replace sash	n/a [	<b>7</b>	Yes		_	\$	
Doors	Repair or replace doors	n/a [	<b>√</b>	Yes			\$	
	Repair or repl. locks/latches	n/a [	7	Yes		Self Help	\$	
Walls/Ceilin	gs							
	Repair or repl. @ defective	n/a [		Yes	1	assorted areas	\$	500.00
Paint	Repair or repl. @ defective	n/a <u>[</u>		Yes	7	_	\$	250.00
Fire Safety		-						
	Install smoke/CO alarm:bsmt.	n/a [		Yes	1	Self Help	\$	50.00
	Install smoke/CO alarm: 1st flr.	n/a [		Yes	7	Self Help	\$	50.00
	Install smoke/CO alarm: 2nd flr.	n/a [		Yes	7	Self Help	\$	50.00
Handrails	Repair/replace defective	n/a [		Yes	7	Self Help	\$	60.00
Stairs	Repair defective	n/a [	7	Yes			\$	
Floors	Denois defective		_	Vaa			ф	1 000 00
Other	Repair defective	n/a [		Yes	7		\$	1,000.00
		n/a [		Yes			\$	
		n/a [		Yes			\$	
		n/a [		Yes			\$	
		n/a [		Yes			\$	
						Interior: Estimated Cost:	\$	5,060.00
						Total Exterior and Interior Cost:*	\$	20,110.00

Inspected by: Andy Yeager Date: 3/8/16

## **Self Help**

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

## **Important Information Regarding Permits**

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located at 7630 W. Mill Road.

<sup>\*</sup>average contracted cost. Actual costs may vary. Self help will reduce the amount.